Test report No. : 11350077H-B-R1
Page : 25 of 27
Issued date : August 4, 2016
FCC ID : VPYLB1FS

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission



Photo 1




Photo 2


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124


: 11350077H-B-R1 Test report No. Page : 26 of 27 Issued date : August 4, 2016 FCC ID : VPYLB1FS

Worst Case Position (Antenna)
Above 1GHz Horizontal: Y-axis/ Vertical: Z-axis) Below 1GHz (Horizontal: Z-axis/ Vertical: Z-axis)


X-axis



Y-axis



Z-axis




4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile : +81 596 24 8124

: 11350077H-B-R1 Test report No. Page : 27 of 27 : August 4, 2016 **Issued date** FCC ID : VPYLB1FS

Worst Case Position (Module)
Above 1GHz (Horizontal: Z-axis/ Vertical: Y-axis) Below 1GHz (Horizontal: X-axis/ Vertical: X-axis)

X-axis



Y-axis



Z-axis



End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile : +81 596 24 8124