Test report No. : 10107589H-R1
Page : 65 of 67
FCC ID : VPYLBYM
Issued date : February 6, 2014
Revised date : February 6, 2014

APPENDIX 4: Photographs of test setup

1. Photographs of host device



Bottom



Front



Rear



Right Side



Left Side




4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 10107589H-R1
Page : 66 of 67
FCC ID : VPYLBYM
Issued date : February 6, 2014
Revised date : February 6, 2014

2. Antenna position




4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 10107589H-R1
Page : 67 of 67
FCC ID : VPYLBYM
Issued date : February 6, 2014
Revised date : February 6, 2014

3. Photographs of setup





End of Report

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124