Test report No. : 10005900H-A-R1
Page : 18 of 19
Issued date : March 15, 2013
Revised date : March 19, 2013
FCC ID : VPYLBXN604

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission



Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124


Test report No. : 10005900H-A-R1
Page : 19 of 19
Issued date : March 15, 2013
Revised date : March 19, 2013
FCC ID : VPYLBXN604

Antenna

Worst Case Position (Horizontal: X-axis/ Vertical: Z-axis)







^{*}The module and antenna will be mounted on a jig board with the same specification as the one used for testing, and it will be installed in the end product.

End of Report

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124