
Test report No. : 13004393S-C-R1
Page : 62 of 64
Issued date : December 23, 2019
FCC ID : VPYLBIVY

APPENDIX 3: Photographs of test setup

Conducted Emission





UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401


 Test report No.
 : 13004393S-C-R1


 Page
 : 63 of 64

 Issued date
 : December 23, 2019

 FCC ID
 : VPYLB1VY

Radiated Spurious Emission







1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No. : 13004393S-C-R1
Page : 64 of 64
Issued date : December 23, 2019
FCC ID : VPYLB1VY

Pre-check of Worst Case Position

Module Antenna













End of Report

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401