Test report No. : 31KE0354-HO-01-B-R1

Page : 12 of 52 Issued date : July 26, 2011 Revised date : July 29, 2011 FCC ID : VPYLBTN

## **APPENDIX 1: Photographs of test setup**

## **Conducted Emission**



Photo 1




Photo 2

# UL Japan, Inc.

### **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 31KE0354-HO-01-B-R1

Page : 13 of 52 Issued date : July 26, 2011 Revised date : July 29, 2011 FCC ID : VPYLBTN

## **Radiated Spurious Emission**



Photo 1



Photo 2

# UL Japan, Inc.

#### **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

: 31KE0354-HO-01-B-R1 Test report No.


Page : 14 of 52 : July 26, 2011 : July 29, 2011 **Issued date** Revised date FCC ID : VPYLBTN

Worst Case Position
Below 1GHz: Horizontal: X-axis/ Vertical: X-axis Above 1GHz: Horizontal: X-axis/ Vertical: Z-axis


#### X-axis



Y-axis



**Z**-axis



## UL Japan, Inc.

#### **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

: +81 596 24 8116 Telephone : +81 596 24 8124 Facsimile