Test report No. : 10180434H-A-R1
Page : 30 of 32
Issued date : February 6, 2014
Revised date : February 12, 2014

Revised date : February 12, 2014 FCC ID : VPYLBSN460

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10180434H-A-R1 Page : 31 of 32

Page : 31 of 32 Issued date : February 6, 2014 Revised date : February 12, 2014 FCC ID : VPYLBSN460

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124


Test report No. : 10180434H-A-R1
Page : 32 of 32
Issued date : February 6, 2014
Revised date : February 12, 2014
FCC ID : VPYLBSN460

Worst Case Position (Horizontal: Y-axis/ Vertical: Z-axis)

X-axis



Y-axis



End of Report

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124