Test report No. : 10300014H-A-R1
Page : 29 of 31
Issued date : May 23, 2014
Revised date : June 4, 2014
FCC ID : VPYLBZY

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc. Ise HQ EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10300014H-A-R1
Page : 30 of 31
Issued date : May 23, 2014
Revised date : June 4, 2014
FCC ID : VPYLBZY

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc. Ise HQ EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10300014H-A-R1
Page : 31 of 31
Issued date : May 23, 2014
Revised date : June 4, 2014
FCC ID : VPYLBZY


Worst Case Position
Above 1GHz (Horizontal: Y-axis/ Vertical:Z-axis)
Below 1GHz (Horizontal: X-axis/ Vertical:X-axis)

X-axis



Y-axis

| Part |



End of Report

UL Japan, Inc. Ise HQ EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124