


FCC ID : VPYLB1LD IC CN : 772C-LB1LD


2DH5, Hopping OFF, 2402MHz








FCC ID : VPYLB1LD IC CN : 772C-LB1LD








Original: April 20, 2017

FCC ID : VPYLB1LD IC CN : 772C-LB1LD


2DH5, Hopping OFF, 2441MHz








FCC ID : VPYLB1LD IC CN : 772C-LB1LD








Original: April 20, 2017

FCC ID : VPYLB1LD IC CN : 772C-LB1LD


2DH5, Hopping OFF, 2480MHz








FCC ID: VPYLB1LD IC CN: 772C-LB1LD








Original: April 20, 2017

FCC ID : VPYLB1LD IC CN : 772C-LB1LD


3DH5, Hopping OFF, 2402MHz








FCC ID : VPYLB1LD IC CN : 772C-LB1LD








Original: April 20, 2017

FCC ID : VPYLB1LD IC CN : 772C-LB1LD


3DH5, Hopping OFF, 2441MHz








FCC ID: VPYLB1LD IC CN: 772C-LB1LD








Original: April 20, 2017

FCC ID : VPYLB1LD IC CN : 772C-LB1LD


3DH5, Hopping OFF, 2480MHz








FCC ID: VPYLB1LD IC CN: 772C-LB1LD





Original: April 20, 2017