Test report No. : 10799281S-A
Page : 31 of 33
Issued date : June 30, 2015
FCC ID : VPYLB1EK

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1



Photo 2

UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No. : 10799281S-A
Page : 32 of 33
Issued date : June 30, 2015
FCC ID : VPYLB1EK

Radiated Spurious Emission




Photo 1




Photo 2




Photo 3

UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

: 10799281S-A Test report No. Page : 33 of 33 **Issued date** : June 30, 2015 FCC ID : VPYLB1EK

Worst Case Position (above 1 GHz: Horizontal: X-axis/ Vertical:Z-axis) (below 1 GHz: Horizontal: X-axis/ Vertical:X-axis)

X-axis



Y-axis



Z-axis



End of Report

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile : +81 463 50 6401