Test report No. : 10689818H-B
Page : 54 of 57
Issued date : June 17, 2015
FCC ID : VPYLB1EN

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1



Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10689818H-B
Page : 55 of 57
Issued date : June 17, 2015
FCC ID : VPYLB1EN

Radiated Spurious Emission



Photo 1



Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

 Test report No.
 : 10689818H-B


 Page
 : 56 of 57


 Issued date
 : June 17, 2015


 FCC ID
 : VPYLB1EN


Antenna Worst Case Position

(Horizontal: Y1(90deg) / Vertical: Y1(0deg)) (Above 1GHz) (Horizontal: X1(0deg) / Vertical: X1(0deg)) (Below 1GHz)













UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10689818H-B Page : 57 of 57 Issued date : June 17, 2015 FCC ID : VPYLB1EN


Module Worst Case Position

(Horizontal: X-axis / Vertical: X-axis) (Above 1GHz) (Horizontal: Y-axis / Vertical: Y-axis) (Below 1GHz)


X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN