

Issue Date: 28 January, 2013 Report No.: RY1301Z28R1 Model: TM10-B/QQ

Test setup photographs 3

Radiated spurious emissions 3.1







Page 19 of 21

RF Technologies Ltd.472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan
Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp



Issue Date: 28 January, 2013 Report No.: RY1301Z28R1 Model: TM10-B/QQ

3.2 AC power line conducted emissions



3.3 Frequency Stability



RF Technologies Ltd.472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan
Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp