



Product Photos





Report No. : FA052502









SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4

: D1 of D2 Page Number Report Issued Date: Jun. 21, 2010

Report Version : Rev. 01



FCC/IC SAR Test Report



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : D2 of D2
Report Issued Date : Jun. 21, 2010
Report Version : Rev. 01

Report No. : FA052502



Test Setup Photos



Primary Landscape



Primary Portrait

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : E1 of E3
Report Issued Date : Jun. 21, 2010
Report Version : Rev. 01

Report No.: FA052502





Secondary Landscape




Secondary Portrait

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : E2 of E3
Report Issued Date : Jun. 21, 2010
Report Version : Rev. 01

Report No.: FA052502





Bottom of Tablet PC Touching with 0 cm Gap

Note: The DUT was integrated into the host (Tablet Computer) during test.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : E3 of E3
Report Issued Date : Jun. 21, 2010
Report Version : Rev. 01

Report No.: FA052502