3. Internal Photograph of EUT


Brand Name: LG / Model Name: LGP43, P430, PB430, PD430, PV430

Report No.: EP140837



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 8 of 13
Report Issued Date : Apr. 27, 2011
Report Version : Rev. 01


Report No.: EP140837



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4

Page Number : 9 of 13 Report Issued Date : Apr. 27, 2011 Report Version : Rev. 01

Report No.: EP140837




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 10 of 13
Report Issued Date : Apr. 27, 2011
Report Version : Rev. 01

Report No.: EP140837



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 11 of 13
Report Issued Date : Apr. 27, 2011
Report Version : Rev. 01

Report No.: EP140837



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 12 of 13
Report Issued Date : Apr. 27, 2011
Report Version : Rev. 01

Report No.: EP140837



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 13 of 13
Report Issued Date : Apr. 27, 2011
Report Version : Rev. 01