



Appendix D. Product Photos





Report No.: FA140837










SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 Page Number : D1 of D1
Report Issued Date : Apr. 26, 2011
Report Version : Rev. 01



Appendix E. Test Setup Photos



Bottom of the DUT with Phantom 0 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 Page Number : E1 of E1
Report Issued Date : Apr. 26, 2011

Report No.: FA140837

Report Version : Rev. 01