



Appendix D. Product Photos





Connector 2: TX/RX (AUX port)

Connector 1: TX/RX (Main port)


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 Page Number : D1 of D1
Report Issued Date : Dec. 19, 2011
Report Version : Rev. 05

Report No.: FA112725-06




Report No.: FA112725-06


Appendix E. Test Setup Photos




Front of the DUT with Phantom 2.4 cm Gap




Back of the DUT with Phantom 2.4 cm Gap



Right Side of the DUT with Phantom 2.4 cm Gap



Left Side of the DUT with Phantom 2.4 cm Gap





Top Side of the DUT with Phantom 2.4 cm Gap Bottom Side of the DUT with Phantom 2.4 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 Page Number : E1 of E1 Report Issued Date: Dec. 19, 2011 Report Version : Rev. 05