


Appendix D. Test Setup Photos



Bottom of the DUT with Phantom 0 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 Page Number : D1 of D1
Report Issued Date : Apr. 23, 2013
Report Version : Rev. 01

Report No. : FA112725-16