


Report No.: FA322231


Appendix D. SAR Test Setup Photos






Right Cheek

Right Tilted





Left Cheek Left Tilted

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQK-F06E Page Number : D1 of D2
Report Issued Date : Apr. 29, 2013

Report Version : Rev. 01




Front of the DUT with Phantom 1 cm Gap



Report No. : FA322231


Back of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQK-F06E Page Number : D2 of D2
Report Issued Date : Apr. 29, 2013
Report Version : Rev. 01