










## Photographs of EUT





















Report No.: 3D1632-04















































Report No.: 3D1632-04































Report No.: 3D1632-04




**SPORTON International Inc.**



TEL : 886-3-327-3456



FAX : 886-3-327-0973

PAGE NUMBER : 29 of 36



ISSUED DATE : May 12, 2016








Tuner Chip: MXL267  
(For Model No.: DPC3941,  
DPC3941T and  
DCP3941XXXX use)







SPORTON LAB.

Report No.: 3D1632-04



