

Appendix A. Test Photos

Report No.: FR312207AN

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973





Report No.: FR312207AN

1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A6 Report Version : Rev. 01



FCC Test Report No.: FR312207AN



SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01


FAX: 886-3-327-0973





2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



Report No.: FR312207AN

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.
TEL: 886-3-327-3456


FAX: 886-3-327-0973

Page No. : A4 of A6 Report Version : Rev. 01




FCC Test Report No.: FR312207AN

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A6 Report Version : Rev. 01




FCC Test Report No.: FR312207AN

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A6 Report Version : Rev. 01