



FCC RADIO TEST REPORT

APPENDIX B. Photographs of EUT




Report No. : FR272809




TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B1 OF B7
ISSUED DATE : Oct. 23, 2012







Report No.: FR272809



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B3 OF B7
ISSUED DATE : Oct. 23, 2012





Report No.: FR272809




TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B4 OF B7
ISSUED DATE : Oct. 23, 2012





Report No. : FR272809




TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B5 OF B7 ISSUED DATE : Oct. 23, 2012





Report No.: FR272809



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B6 OF B7
ISSUED DATE : Oct. 23, 2012



FCC RADIO TEST REPORT



ISSUED DATE : Oct. 23, 2012

Report No.: FR272809

SPORTON International Inc. PAGE NUMBER: B7 OF B7

TEL: 886-3-327-3456 FAX: 886-3-327-0973