Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : A1 of A7
TEL: 886-3-327-3456 Report Version : Rev. 02




1 Photographs of Conducted Emissions Test Configuration

Mode 1



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A7 TEL: 886-3-327-3456 Report Version : Rev. 02






SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A7 TEL: 886-3-327-3456 Report Version : Rev. 02




2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



: A4 of A7

: Rev. 02


REAR VIEW

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version




For radiated emissions 30MHz~1GHz

Mode 2



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A5 of A7 TEL: 886-3-327-3456 Report Version : Rev. 02



For radiated emissions above 1GHz

Mode 2



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A6 of A7 TEL: 886-3-327-3456 Report Version : Rev. 02






Report No.: FR452224



EUT took a close view



EUT took a close view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A7 of A7
Report Version : Rev. 02