




Appendix A. Test Photos 1. Photographs of Conducted Emissions Test Configuration Mode 1



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A8

Report Version

: Rev. 01

Report No.: FR5O2901-01AD





Report No.: FR5O2901-01AD

SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01





Mode 2



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A8

Report Version : I

: Rev. 01

Report No.: FR5O2901-01AD





Report No. : FR5O2901-01AD



SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A4 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01



FCC Test Report Report No.: FR5O2901-01AD

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A5 of A8 TEL: 886-3-327-3456 Report Version : Rev. 01





For radiated emissions 30MHz~1GHz

Mode 1



Report No.: FR5O2901-01AD

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A6 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01






Report No. : FR5O2901-01AD


: A7 of A8

: Rev. 01

Mode 2



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version



CC Test Report No. : FR5O2901-01AD

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A8 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01