


Report No.: FA072825-06

## Appendix D. Product Photos



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMF33072-A Page Number : D1 of D3
Report Issued Date : Mar. 22, 2011
Report Version : Rev. 01



## FCC SAR Test Report



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMF33072-A Page Number : D2 of D3
Report Issued Date : Mar. 22, 2011
Report Version : Rev. 01

Report No.: FA072825-06



## **Antenna Location:**



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMF33072-A Page Number : D3 of D3
Report Issued Date : Mar. 22, 2011
Report Version : Rev. 01

Report No.: FA072825-06



## Appendix E. Test Setup Photos



Bottom of the DUT with Phantom 0 cm Air Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VV7-MBMF33072-A Page Number : E1 of E1 Report Issued Date: Mar. 22, 2011

Report No.: FA072825-06

Report Version : Rev. 01