



APPENDIX B. Photographs of EUT






TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B1 OF B16
ISSUED DATE : Jun. 27, 2014








TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B2 OF B16
ISSUED DATE : Jun. 27, 2014









TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B3 OF B16











TEL: 886-3-327-3456 FAX: 886-3-327-0973









TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B11 OF B16
ISSUED DATE : Jun. 27, 2014







TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B12 OF B16






Adapter 1

50 40 90 80 70 60 50 40 30 20 10 mm

09 09 07 08 07 01

Report No.: EP411403-01



TEL: 886-3-327-3456 FAX: 886-3-327-0973







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B15 OF B16





TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B16 OF B16