
## Test setup photographs





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1 Trig Avionics Limited Models: TY 96 and TY 97


Test #: 160412


Test to: CFR47 Parts 2, 87 and RSS-141  $\,$ 

File: TY9697 TSup

SN: ENG9 FCC: VZI01228 IC: 10614A-01228 Date: May 16, 2016

Page 1 of 3





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1 Trig Avionics Limited Models: TY 96 and TY 97


Test #: 160412


Test to: CFR47 Parts 2, 87 and RSS-141  $\,$ 

File: TY9697 TSup

SN: ENG9 FCC: VZI01228 IC: 10614A-01228 Date: May 16, 2016

Page 2 of 3





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1 Trig Avionics Limited Models: TY 96 and TY 97

Test #: 160412

Test to: CFR47 Parts 2, 87 and RSS-141  $\,$ 

File: TY9697 TSup

SN: ENG9 FCC: VZI01228 IC: 10614A-01228 Date: May 16, 2016

Page 3 of 3