Test report No. : 31JE0038-SH-01-A-R1

Page : 47 of 48
Issued date : June 22, 2012
FCC ID : W2Z-01000004

### **APPENDIX 3: Photographs of test setup**

# **Radiated Spurious Emission**




Photo 1




Photo 2

### UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401


Test report No. : 31JE0038-SH-01-A-R1

Page : 48 of 48
Issued date : June 22, 2012
FCC ID : W2Z-01000004

### **Worst Case Position**

(Below 1GHz Horizontal: Z-axis / Vertical: X-axis Above 1GHz Horizontal: Y-axis / Vertical: X-axis)

X-axis







## UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401