Test report No.
 : 11925091S-A-R1

 Page
 : 61 of 63

 Issued date
 : September 7, 2017

 FCC ID
 : W2Z-02000004

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1



Photo 2

UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401


 Test report No.
 : 11925091S-A-R1

 Page
 : 62 of 63

 Issued date
 : September 7, 2017

 FCC ID
 : W2Z-02000004

Radiated Spurious Emission




Front (below 1 GHz)



Front (above 1 GHz)



Rear (below 1 GHz)



Rear (above 1 GHz)

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No. : 11925091S-A-R1
Page : 63 of 63
Issued date : September 7, 2017
FCC ID : W2Z-02000004

Worst Case Position







End of Report

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401