Test report No. : 11143372S-B-R1
Page : 110 of 113
Issued date : June 6, 2016
FCC ID : W2Z-01000008

APPENDIX 3: Photographs of test setup

Conducted Emission



Front




Side


UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Test report No. : 11143372S-B-R1
Page : 111 of 113
Issued date : June 6, 2016
FCC ID : W2Z-01000008

Radiated Spurious Emission







UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Test report No. : 11143372S-B-R1
Page : 112 of 113
Issued date : June 6, 2016
FCC ID : W2Z-01000008

Worst Case Position

(module)



Y-axis






1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

: 11143372S-B-R1 Test report No. Page : 113 of 113 **Issued date** : June 6, 2016 FCC ID : W2Z-01000008


Worst Case Position







(Antenna 1)









End of Report

UL Japan, Inc. **Shonan EMC Lab.**

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN