

Test report No. : 11151247S-A-R2
Page : 47 of 49
Issued date : March 22, 2016
FCC ID : W2Z-03000003

APPENDIX 3: Photographs of test setup

Conducted Emission





UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No. : 11151247S-A-R2
Page : 48 of 49
Issued date : March 22, 2016
FCC ID : W2Z-03000003

Radiated Spurious Emission







UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No. : 11151247S-A-R2
Page : 49 of 49
Issued date : March 22, 2016
FCC ID : W2Z-03000003

Pre-check of the worst position





End of Report

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401