Test report No. : 10003907H-A-R1
Page : 54 of 56
Issued date : March 18, 2013
Revised date : March 27, 2013
FCC ID : W2Z-02100002

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 10003907H-A-R1
Page : 55 of 56
Issued date : March 18, 2013
Revised date : March 27, 2013
FCC ID : W2Z-02100002

Radiated Spurious Emission



Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124


Test report No. : 10003907H-A-R1
Page : 56 of 56
Issued date : March 18, 2013
Revised date : March 27, 2013
FCC ID : W2Z-02100002

Worst Case Position (Horizontal: X-axis/ Vertical: Y-axis)


X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124