Test report No.
 : 11689535H-A

 Page
 : 47 of 49

 Issued date
 : June 27, 2017

 FCC ID
 : W2Z-03000005

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11689535H-A
Page : 48 of 49
Issued date : June 27, 2017
FCC ID : W2Z-03000005

Radiated Spurious Emission




Photo 1




Photo 2


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

: 11689535H-A Test report No. Page : 49 of 49 Issued date : June 27, 2017 FCC ID : W2Z-03000005

Worst Case Position
Above 1 GHz:(Horizontal: Z-axis/ Vertical:Y-axis) Below 1 GHz: (Horizontal: X-axis/ Vertical: X-axis)





Y-axis



Z-axis



End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile : +81 596 24 8124