

Report No.: FR450632

# **Appendix A. Test Photos**

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973





# 1 Photographs of Conducted Emissions Test Configuration



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A6

Report Version

: Rev. 01

Report No.: FR450632



FCC Test Report

Report No.: FR450632



**SIDE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973






**Report No. : FR450632** 

# 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A4 of A6 TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973




FCC Test Report

Report No.: FR450632

### For radiated emissions 30MHz~1GHz



### **FRONT VIEW**



## **REAR VIEW**

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A5 of A6


Report Version : Rev. 01



# FCC Test Report

Report No.: FR450632

### For radiated emissions above 1GHz



## FRONT VIEW



### **REAR VIEW**

SPORTON INTERNATIONAL INC. Page
TEL: 886-3-327-3456 Repo

FAX: 886-3-327-0973

Page No. : A6 of A6
Report Version : Rev. 01