FCC Test Report Report No.: FR382756

# **Appendix A. Test Photos**

SPORTON INTERNATIONAL INC. Page No. : A1 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973




FCC Test Report No.: FR382756

## 1 Photographs of Conducted Emissions Test Configuration



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A5

Report Version : Rev. 01



FCC Test Report No. : FR382756



**SIDE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973




FCC Test Report No.: FR382756


### 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz

**Transmitter Mode** 



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A5 Report Version : Rev. 01




FCC Test Report **Report No.: FR382756** 

For radiated emissions 30MHz~1GHz

**Transmitter Mode** 



### **FRONT VIEW**



#### **REAR VIEW**

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A5 of A5 : Rev. 01

Report Version