## WARNING!

- 1. MISCONNECTIONS MAY CAUSE DAMAGE TO CONTROL MODEL: 2GIG-CNTRL2-345 PANEL ELECTRONICS.
- 2. DO NOT REVERSE BATTERY LEADS.
- TELCO JACK BEFORE SERVICING.

## **CAUTION!**

- AWAY FROM INTERNAL COMPONENTS.
- 3. REMOVE AC POWER BEFORE CONNECTING TRANSFORMER OR BATTERY.

## IMPORTANT! 1. WEEKLY TESTING IS REQUIRED TO ENSURE PROPER

- OPERATION OF THE SYSTEM. 2. DO NOT CONNECT AC POWER TO A RECEPTACLE En conformité avec IC CNR 210.
- CONTROLLED BY A SWITCH. 3. CONNECTION OF THE FIRE ALARM SIGNAL TO A FIRE ALARM
- HEADQUARTERS OR A CENTRAL STATION SHALL BE PERMITTED

  Fire protection Regulatory Information

  Fire protection must follow NFPA Standard No. 72 (National Fire BE CONNECTED TO A POLICE EMERGENCY NUMBER.

Refer to drawing 230373 Revision A, dated 9/2009 for to be provided with this equipment proper installation and wiring diagram. Pat. 6,928,148

## RESIDENTIAL SECURITY RECEIVER

FREQUENCY: 345 MHZ

POWER SUPPLY: 14 VDC, 1.7 A

3. TO PREVENT RISK OF ELECTRICAL SHOCK, DISCONNECT This device complies with FCC Part 15 and Industry Canada rules and regulations. Operation is subject to the following two conditions: (1) This device may not cause harmful interference and (2) this device must accept any interference received, including No USER SERVICEABLE PARTS INSIDE.
 RISK OF FIRE AND ELECTRICAL SHOCK, ROUTE WIRES
 AWAY FROM INTERNAL COMPONENTS
 Part 15 of the FCC Rules. See instructions if interference to radio
 Part 15 of the FCC Rules. See instructions if interference to radio reception is suspected.

United States Regulatory Information FCC ID: WDQ-CNTRLX345 Complies with Part 68, FCC Rules. FCC Registration Number: WDQAL04BCNTRLX345 Ringer Equivalence Number: .41 B

500

αi

Canadian Regulatory Information IC: 7794A-CNTRLX345 Complies with IC RSS 210

Optional GSM/GPRS Radio Information IC: 4160A GSM0308 or 5131A-GE865

ONLY WITH THE APPROVAL OF THE LOCAL AUTHORITY HAVING
Protection Association, Batterymarch Park, Quincy, MA 02269). JURISDICTION. THE BURGLAR ALARM SIGNAL SHALL NOT Printed information describing proper installation, operation, be rounierted to a point full receivery willinking testing, maintenance, evacuation planning, and repair service is

230076 DX1 MADE IN CHINA 454 2gig technologies

LABEL, FCC, 2GIG-CNTRL2-345 LINEAR P/N: 230076 DX1

MFG. PROCESS: PRINTED LABEL OR PAD PRINTING

LABEL MATERIAL: 60 LB. WHITE COATED, ADHESIVE BACKED

LABEL INK: PERMANENT BLACK

PAD PRINTING INK: BLACK, LINEAR P/N 213337-002

SCALE: 1-1