

page 1 of 8

Annex B External photos




172189_eut1: Top view

 Test engineer:
 Michael DINTER
 Report Number:
 F172189E1

 Date of issue:
 16.02.2018
 Order Number:
 17-112189





172189_eut2: 3D view

 Test engineer:
 Michael DINTER
 Report Number:
 F172189E1

 Date of issue:
 16.02.2018
 Order Number:
 17-112189

ber: 17-112189 page 2 of 8





172189_eut3: Bottom view

 Test engineer:
 Michael DINTER
 Report Number:
 F172189E1

 Date of issue:
 16.02.2018
 Order Number:
 17-112189

page 3 of 8



page 4 of 8

Annex B External photos



172189_eut4: Bottom view cover removed

 Test engineer:
 Michael DINTER
 Report Number:
 F172189E1

 Date of issue:
 16.02.2018
 Order Number:
 17-112189





172189_eut5: View type plate

 Test engineer:
 Michael DINTER
 Report Number:
 F172189E1

 Date of issue:
 16.02.2018
 Order Number:
 17-112189
 page 5 of 8






172189_eut6: View connectors

 Test engineer:
 Michael DINTER
 Report Number:
 F172189E1

 Date of issue:
 16.02.2018
 Order Number:
 17-112189

page 6 of 8





172189_eut30: Top view connectors

 Test engineer:
 Michael DINTER
 Report Number:
 F172189E1

 Date of issue:
 16.02.2018
 Order Number:
 17-112189

page 7 of 8





172189_eut32: View Typeplate AC adapter

 Test engineer:
 Michael DINTER
 Report Number:
 F172189E1

 Date of issue:
 16.02.2018
 Order Number:
 17-112189
 page 8 of 8