


144371_emi1

 Testengineer:
 Michael DINTER
 Report Number:
 F144371E1

 Date of issue:
 16 September 2014
 Order Number:
 14-114371
 page 1 of 10





144371_emi2

 Testengineer:
 Michael DINTER
 Report Number:
 F144371E1

 Date of issue:
 16 September 2014
 Order Number:
 14-114371
 page 2 of 10






144371_emi3

 Testengineer:
 Michael DINTER
 Report Number:
 F144371E1

 Date of issue:
 16 September 2014
 Order Number:
 14-114371
 page 3 of 10





144371_emi4

 Testengineer:
 Michael DINTER
 Report Number:
 F144371E1

 Date of issue:
 16 September 2014
 Order Number:
 14-114371
 page 4 of 10






144371_emi5

 Testengineer:
 Michael DINTER
 Report Number:
 F144371E1

 Date of issue:
 16 September 2014
 Order Number:
 14-114371
 page 5 of 10





144371_emi6

 Testengineer:
 Michael DINTER
 Report Number:
 F144371E1

 Date of issue:
 16 September 2014
 Order Number:
 14-114371
 page 6 of 10





144371_emi7

 Testengineer:
 Michael DINTER
 Report Number:
 F144371E1

 Date of issue:
 16 September 2014
 Order Number:
 14-114371
 page 7 of 10





144371_emi8

 Testengineer:
 Michael DINTER
 Report Number:
 F144371E1

 Date of issue:
 16 September 2014
 Order Number:
 14-114371
 page 8 of 10





144371_emic1

 Testengineer:
 Michael DINTER
 Report Number:
 F144371E1

 Date of issue:
 16 September 2014
 Order Number:
 14-114371
 page 9 of 10





144371_emic2

 Testengineer:
 Michael DINTER
 Report Number:
 F144371E1

 Date of issue:
 16 September 2014
 Order Number:
 14-114371
 page 10 of 10