

page 1 of 6

Test setup photos Annex A



181775_fcc_01: Test setup fully anechoic chamber > 30 MHz

Examiner: Michael DINTER Date of issue: 08.04.2019

Report Number: F181775E1 Order Number: 18-111775





181775_fcc_02: Test setup fully anechoic chamber > 30 MHz

 Examiner:
 Michael DINTER
 Report Number:
 F181775E1

 Date of issue:
 08.04.2019
 Order Number:
 18-111775

 page 2 of 6





181775_fcc_03: Test setup fully anechoic chamber > 1GHz

 Examiner:
 Michael DINTER
 Report Number:
 F181775E1

 Date of issue:
 08.04.2019
 Order Number:
 18-111775

page 3 of 6



page 4 of 6

Test setup photos Annex A



181775_fcc_04: Test setup outdoor test site

Report Number: F181775E1 Order Number: 18-111775

Examiner: Michael DINTER Date of issue: 08.04.2019






181775_fcc_05: Test setup open area test site

 Examiner:
 Michael DINTER
 Report Number:
 F181775E1

 Date of issue:
 08.04.2019
 Order Number:
 18-111775

 page 5 of 6
 page 5 of 6





181775_fcc_06: Test setup fully anechoic chamber < 1GHz

 Examiner:
 Michael DINTER
 Report Number:
 F181775E1

 Date of issue:
 08.04.2019
 Order Number:
 18-111775

Number: 18-111775 page 6 of 6