

# **Appendix A. Test Photos**

**Report No. : FR550401** 

SPORTON INTERNATIONAL INC. Page No. : A1 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973



FCC Test Report No.: FR550401

## 1 Photographs of Conducted Emissions Test Configuration



**FRONT VIEW** 



Page No.

Report Version

: A2 of A5

: Rev. 01


**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973



FCC Test Report Report No.: FR550401



**SIDE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01


FAX: 886-3-327-0973






### 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**Report No.: FR550401** 

**FRONT VIEW** 



**REAR VIEW** 


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A5 Report Version : Rev. 01




FCC Test Report No.: FR550401

#### For radiated emissions 30MHz~1GHz



#### **FRONT VIEW**



### **REAR VIEW**

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A5

Report Version : Rev. 01