
Test report No.: 10004105S Page : 23 of 25

# **APPENDIX 3: Photographs of test setup**

#### **Conducted emission**





### UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka Hiratsuka-shi Kanagawa-ken 259-1220 JAPAN

Telephone Facsimile : +81 463 50 6400 : +81 463 50 6401

Test report No.: 10004105S Page: 24 of 25

# **Radiated emission**




Rear (below 30MHz) Horizontal



Rear (below 30MHz) Vertical



Rear (above 30MHz)



#### UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka Hiratsuka-shi Kanagawa-ken 259-1220 JAPAN


Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401

Test report No.: 10004105S Page: 25 of 25


# Pre-check of worst position

X-axis





Z-axis



**END OF REPORT** 

### UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka Hiratsuka-shi Kanagawa-ken 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401