Test report No. : 11439195H-A-R1 : 17 of 20 Page

Issued date : December 5, 2016 FCC ID : WKE-721021

APPENDIX 3: Photographs of test setup

Radiated Emission



Photo 1



Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Test report No. : 11439195H-A-R1 : 18 of 20 Page

Issued date : December 5, 2016 FCC ID : WKE-721021

Radiated Emission



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Test report No. : 11439195H-A-R1
Page : 19 of 20

Issued date : December 5, 2016 FCC ID : WKE-721021

Worst case position

Below 1GHz


Horizontal: X-axis / Vertical: Y-axis


Above 1GHz

Horizontal: X-axis / Vertical: Y-axis









UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11439195H-A-R1 Page : 20 of 20

Issued date : December 5, 2016 FCC ID : WKE-721021

Worst case position



Antenna OUT (Worst)



Antenna IN

End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124