



FCC Test Report

Report No. : FR4D3129-02

APPENDIX B. Photographs of EUT







TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B1 of B8 Report Version : Rev. 01










Page Number : B2 of B8 Report Version : Rev. 01

Report No.: FR4D3129-02











Report No. : FR4D3129-02











Page Number : B4 of B8
Report Version : Rev. 01

Report No.: FR4D3129-02











Page Number : B5 of B8 Report Version : Rev. 01

Report No.: FR4D3129-02










Page Number : B6 of B8
Report Version : Rev. 01

Report No. : FR4D3129-02









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B7 of B8

Report Version : Rev. 01

Report No. : FR4D3129-02







Report No. : FR4D3129-02



TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B8 of B8
Report Version : Rev. 01