

Report No. : FR4D3129-02

Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01





Report No. : FR4D3129-02

1 Photographs of Conducted Emissions Test Configuration

(Mode 1)



FRONT VIEW



Page No.

Report Version

: A2 of A6

: Rev. 01

REAR VIEW

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456







Report No. : FR4D3129-02

SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01






2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



Report No. : FR4D3129-02

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A6 Report Version : Rev. 01




FCC Test Report


Report No. : FR4D3129-02

For radiated emissions 30MHz~1GHz

(Mode 1)



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A5 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01



FCC Test Report


For radiated emissions above 1GHz

(Mode 2)



Report No. : FR4D3129-02

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A6 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01