

Report No.: FR3D0603AC

Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01




1 Photographs of Conducted Emissions Test Configuration

Mode 2



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01






SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01




2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.
TEL: 886-3-327-3456


FAX: 886-3-327-0973

Page No. : A4 of A6 Report Version : Rev. 01




For radiated emissions 30MHz~1GHz

Mode 2



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A5 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01



FCC Test Report


For radiated emissions above 1GHz

Mode 2



Report No.: FR3D0603AC

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A6 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01