
Report No.: EP880720

1. External Photographs of EUT




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM6661 Page Number : 1 of 23 Issued Date : Oct. 06, 2008 Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM6661 Page Number : 2 of 23 Issued Date : Oct. 06, 2008 Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM6661 Page Number : 3 of 23 Issued Date : Oct. 06, 2008 Report Version : Rev. 01

Report No.: EP880720



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM6661 Page Number : 4 of 23 Issued Date : Oct. 06, 2008 Report Version : Rev. 01



Model Name: WM66-61


Report No.: EP880720



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM6661

Page Number : 5 of 23 Issued Date : Oct. 06, 2008 Report Version : Rev. 01

Report No.: EP880720



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM6661 Page Number : 6 of 23
Issued Date : Oct. 06, 2008
Report Version : Rev. 01

otographs of EUT Report No.: EP880720

2. Photographs of Accessories



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM6661 Page Number : 7 of 23 Issued Date : Oct. 06, 2008 Report Version : Rev. 01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM6661 Page Number : 8 of 23 Issued Date : Oct. 06, 2008 Report Version : Rev. 01

Report No.: EP880720