



## Appendix D. Product Photos



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM340 Page Number : D1 of D2
Report Issued Date : May 30, 2012
Report Version : Rev. 01

**Report No. : FA233002** 





TEL: 886-3-327-3456 FAX: 886-3-328-4978


FCC ID:

Page Number : D2 of D2
Report Issued Date : May 30, 2012
Report Version : Rev. 01



## Report No.: FA233002


## Appendix E. Test Setup Photos



Front of the DUT with Phantom 1 cm Gap



Back of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WLPWM340 Page Number : E1 of E1
Report Issued Date : May 30, 2012
Report Version : Rev. 01