
New battery in receiver

We need to discuss this... that small plastic indent will not be present in production units



Scroll down



3 parts populated on back of Transmitter PCB. These pads were present in the previous design (but not populated) The circuit and traces nearby nearby were changed (see schematic)