



attn: Reviewing Engineer Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

Monday, October 14, 2013

To Whom It May Concern:

The BC91/005010, BC91/005011, BC91/005012, BC91/005013, BC91/005014 FCC ID: WONBC91005010 and label is so small that it cannot include the statement specified in FCC Part 15 Sub-part A, Section 15.19 (a) (3) "This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference and
- (2) This device must accept any interference received, including interference that may cause undesired operation."

  Due to this reason, we are using the provisions of Part 15 Sub-part A,

  Section 15.19 (a) (5) and this testament appears in a prominent location in the user manual.

Sincerely,

Yossi Nurok

Hardware engineer

Yossi Nurok

Precyse Technologies Inc Tel: 972-3-9227093 Mobile: 972-54-4482062 Fax: 972-3-9227515