Test report No.
 : 12418148S-A-R1

 Page
 : 33 of 35

 Issued date
 : August 30, 2018

 FCC ID
 : WQYCMX01

## **APPENDIX 3: Photographs of test setup**

## **Conducted Emission**





#### UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401


 Test report No.
 : 12418148S-A-R1

 Page
 : 34 of 35

 Issued date
 : August 30, 2018

 FCC ID
 : WQYCMX01

# **Radiated Spurious Emission**





Rear (above 1 GHz)



#### UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401


 Test report No.
 : 12418148S-A-R1


 Page
 : 35 of 35


 Issued date
 : August 30, 2018

 FCC ID
 : WQYCMX01

# **Worst Case Position**







**End of Report** 

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401