Test report No.
 : 11333790S-A-R3

 Page
 : 34 of 36

 Issued date
 : April 12, 2018

 FCC ID
 : WQYTPZM01

APPENDIX 3: Photographs of test setup

Conducted Emission






UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No. : 11333790S-A-R3
Page : 35 of 36
Issued date : April 12, 2018
FCC ID : WQYTPZM01

Radiated Spurious Emission



Rear





UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401


Test report No. : 11333790S-A-R3
Page : 36 of 36
Issued date : April 12, 2018
FCC ID : WQYTPZM01

Worst Case Position






Y-axis



Z-axis



End of Report

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401