Test report No. : 32BE0001-HO-01-A

Page : 16 of 18

Issued date : September 26, 2011 FCC ID : WRKRI-44BTY

APPENDIX 3: Photographs of test setup

Radiated Emission



Photo 1




Photo 2

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124


Test report No. : 32BE0001-HO-01-A

Page : 17 of 18

Issued date : September 26, 2011 FCC ID : WRKRI-44BTY

Worst Case Position

Below 30MHz (Controller: X-axis / Antenna: X-axis) Above 30MHz (Controller: Horizontal: X-axis, Vertical: X-axis) Above 30MHz (Antenna: Horizontal: X-axis, Vertical: X-axis)



UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

: 32BE0001-HO-01-A Test report No.

Page : 18 of 18


Issued date FCC ID : September 26, 2011 : WRKRI-44BTY

Worst case position

Mechanical Key (Inserted)







UL Japan, Inc. **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124